

TRUESDAIL LABORATORIES, INC.

CHEMISTS - MICROBIOLOGISTS - ENGINEERS
RESEARCH - DEVELOPMENT - TESTING14201 FRANKLIN AVENUE
TUSTIN, CALIF. 92680
AREA CODE 714 • 730-6239
AREA CODE 213 • 225-1564
FAX 714 • 730-8482CLIENT: Douglas Aircraft Company
Internal Mail Code 74-41
3855 Lakewood Blvd.
Long Beach, CA 90846
ATTN: Ron Fornator

REPORT DATE: December 10, 1991

RECEIVED: November 22, 1991

LABORATORY NUMBER: 48713

Water from Stormdrain, Torrance Facility
P.O. No: T & M 25998CQuarterly and Monthly, Analysis as Required by NPDES Permit #CA0001414
Fourth Quarter and November, 1991RESULTS

A one gallon grab sample was taken from the stormdrain at 12:25pm on November 22, 1991, by a representative of Truesdail Laboratories, Inc. The results are as follows:

Total Flow, GPD
Temperature, °F
pH, Units (EPA 150.1)1,141
70
8.0

Parameter	Method	MILLIGRAMS PER LITER	
		Detection Limit	Concentration
Biochemical Oxygen Demand	405.1	2.0	ND
Oil and Grease	413.1	6.0	ND
Settleable Solids	160.5	0.10	1.5
Total Suspended Solids	160.2	4.0	52.0

*ND = Not detected, below detection limit

Respectfully Submitted,
Truesdail Laboratories, Inc.Julia Nayberg, Manager
Inorganic Chemistry

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from these Laboratories.